TITLE 267 - NEBRASKA OIL AND GAS CONSERVATION COMMISSION

CHAPTER 3 - DRILLING, DEVELOPMENT, PRODUCING AND ABANDONMENT

019 MEASUREMENT OF GAS

Production of gas of all kinds, with the exception of gas used on the lease and small amounts of gas produced with oil, as excepted by the Director, shall be measured by orifice type meter or other type meter approved by the Director. The standard of pressure shall be 14.73 pounds per square inch absolute and the standard of temperature shall be 60° F., regardless of the atmospheric pressure and temperature at the point of measurement. All volumes of gas to be reported to the Commission shall be adjusted by computation to these standards unless otherwise authorized by the Director.