TITLE 267 - NEBRASKA OIL AND GAS CONSERVATION COMMISSION

CHAPTER 3 - DRILLING, DEVELOPMENT, PRODUCING AND ABANDONMENT

029 PLUGGING OF SEISMIC AND STRATIGRAPHIC TESTS

It shall be the duty of any person, operator or contractor drilling a seismic or stratigraphic test hole, regardless of diameter or depth, whether cased or uncased, to plug said hole in a manner sufficient to properly protect all fresh water bearing and possible or probable oil or gas bearing formations.